




Impressiontaking

Preparation

Optimization of the impression

Fill and place into position 0-30 seconds











Removal: 1:30-2:20 minutes

Finishing: After 5:00 Minutes

Surface processing and polishing

Permanentor temporary cementation

Placement