

LuxaCrown

For your patient emergencies




Clinicians are faced with unique challenges that include emergency situations every day. In those critical moments, LuxaCrown is the crown and bridge material that meets both clinical and patient expectations at a viable, lower cost alternative to traditional crown and bridge restorations.

The following cases demonstrate the versatility and practicality of LuxaCrown in critical real-life moments:



Case 1

A ten-year-old girl presented with an extensive fracture of the left central incisor #9.




Case 2

A healthy male patient presented with teeth #9 and #11 broken off due to failure of an old three-unit fixed porcelain-fused-to-metal bridge.



Case 3

A patient presented with tooth #12 requiring a new full coverage crown due to the existing crown fracturing off. The patient, however, stated that she would be leaving the country the next day for several months.

 For more information or to schedule a virtual appointment, please contact your DMG representative.

